


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 5- -96 To (mo./yr.) 10-11-96
2. DOGM File Number (Mine No): S/053/050
3. Mine Name: Dolomite Stone #1
4. Mineral(s) Mined (or permitted to mine): Dolomite Stone & Minerals
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
NW 1/4, NW 1/4, Section 10, Township 39S, Range 19W
____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
7. Name of Operator or Company: Stephen LAUB
8. Permanent Street Address: "None" P.O. Box 400
City, State, Zip: Santa Clara, Utah 84765
Phone: 801-673-9308
9. Company Representative (or designated operator):
Name: Stephen LAUB
Title: OWNER
Business Address: P.O. Box 400, Motoqua UT Ranch
City, State, Zip: Santa Clara, Utah 84765
Phone: _____

☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☒ ^{AND}
2. If active, how much ore or mineral was mined? ONLY TESTING & preparing ACCESS FOR THE REMOVAL OF MINERAL STONE and Precious metal and Material

3. How much additional acreage was disturbed during the past year? NONE
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

ONLY ACCESS Road To The Old Quarry
Site AND The FRONT Side OF Stone Vein
AS was Already Exposed IN year's
PAST (This was Accomplished with small Dozer))

5. How much acreage was reclaimed during the past year? NONE
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Saving ANY Soil or Material For Use
IN Time To Come AT site .

7. What is the total disturbed acreage at years end? Less Than 1. Acre

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

when Access permits will Start To work
The Vein AT Quarry Site Hauling OUT Material
With Small Truck AND Bringing Back Soil
For use IN Future Reclaiming project.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

STEPHEN LAUB

Title of Operator:

OWNER

Signature of Operator:

Stephen Laub

Date:

1-24-97